

**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	247.003	247.012	247.014	247.084	247.087	
L	Left-hand drive	○	○	○	○	○	0,00
R	Right-hand drive	●	●	●	●	●	1113,00
149U	polar white	●	●	●	●	●	0,00
191U	cosmos black metallic	●	●	●	●	●	619,50 295,00 398,25
589U	jupiter red	○	○	○	○	○	0,00
623U	light ivory 1_only in conjunction with Code 965 2_not valid, only for Code 017	○	○	U	U	U	0,00
662U	designo mountain grey magno	●	●	●	●	●	1942,50
667U	denim blue metallic	●	●	●	●	●	619,50 295,00 398,25
775U	iridium silver metallic	●	●	●	●	●	619,50 295,00 398,25
787U	mountain grey metallic	●	●	●	●	●	619,50 295,00 398,25
101A	Black ARTICO man-made leather 1_nur in Verbindung mit Code P27 oder P59 and 7U2	●	●	●	●	●	152,25
105A	ARTICO man-made leather macchiato beige / black 1_only in conjunction with Code P59 an 7U2	●	●	●	●	●	152,25
159A	Two-tone ARTICO man-made leather neva grey / black 1_only in conjunction with Code 950 and 7U4	○	○	○	○	○	0,00
201A	Leather black 1_only in conjunction with Code P34 and P59 and 7U2 2_only in conjunction with Code 873 or 401	○	○	○	○	○	0,00
205A	Leather macchiato beige / black 1_only in conjunction with Code P34, P59 and 7U2 2_only in conjunction with Code 873 or 401	○	○	○	○	○	0,00
211A	Leather black 1_only in conjunction with Code P34 and P59 or 950 and 7U4 2_only in conjunction with Code 873 oder 401	○	○	○	○	○	0,00
257A	Leather, two-tone classic red / black 1_only in conjunction with Code P39 and 950 and 7U4 2_only in conjunction with Code 873 or 401	○	○	○	○	○	0,00
258A	Leather, two-tone titanium grey pearl / black 1_only on conjunction with Code P39 and 950 and 7U4 2_not in conjunction with Code 874 or 401	○	○	○	○	○	0,00
301A	ARTICO man-made leather / Tandel fabric black 1_only in conjunction with Code 7U1 2_not in conjunction with Code 950, P27, P59 3_for certain countries only	○	○	○	○	○	0,00
311A	ARTICO man-made leather / Bertrix fabric black 1_only in conjunction with Code P27 and 7U2 2_for certain contries only	○	○	○	○	○	0,00
321A	ARTICO man-made leather / Fléron fabric black 1_only in conjunction with Code P59 and 7U2	○	○	○	○	○	0,00
371A	ARTICO man-made leather/ Bertrix fabric two-tone black / neva grey 1_only in conjunction with Code P27 and 7U2 2_for certain countries only	○	○	○	○	○	0,00
372A	ARTICO man-made leather / Bertrix fabric indigo blue / black 1_only in conjunction with Code P27 and 7U2 2_for certain countries only	○	○	○	○	○	0,00
381A	ARTICO man-made leather/ Fléron fabric, two-tone black / Bahia brown 1_only in conjunction with Code P59 and 7U2	○	○	○	○	○	0,00
411	6-speed manual transmission 1_only for certain countries 2_not valid	U ★	U ★	-	S	S	0,00

**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	247.003 B 180 d	247.012 B 200 d	247.014 B 220 d	247.084 B 180	247.087 B 200	
426	<b>8G-DCT</b> 1_not in conjunction with Code U63	-	S	S	-	-	0,00
429	<b>7G-DCT</b> 1_not in conjunction with Code U63	S	-	-	-	-	0,00
		-	-	-	●	●	1188,00
651A	<b>ARTICO man-made leather / microfibre DINAMICA black</b> 1_only in conjunction with Code 950 and 7U4	○	○	○	○	○	0,00
22P	<b>Lane Tracking package</b> 1_only in conjunction with Code 234 and 243 2_not in conjunction with Code 23P, 51B	●	●	●	●	●	819,00
23P	<b>Driving Assistance package</b> 1_only in conjunction with Code 233 and 299 and 275 or P49 <b>i.V.m. Code 51B</b>	●	●	●	●	●	1995,00
		●	●	●	●	●	1585,50
431	<b>Galvanised steering-wheel gearshift paddles</b> 1_only in conjunction with Code 426 or 429 and L5C or L5I 2_not in conjunction with Code 428	○	○	○	○	○	0,00
950	<b>AMG line</b> 1_only in conjunction with Code 159A, 211A, 257A, 258A, 651A. Code H62, H15, H23 or H44, 677, 459 or 485, 772, 310, B63 (f. c. engines), Code RQS, RQT, RVG or RVK, U26, L5C or L5I 2_not in conjunction with Code P27, P59 3_for certain countries only <b>i.V.m. Code PYH</b>	●	●	●	●	●	3097,50
		○	○	○	○	○	0,00
P17	<b>KEYLESS-GO Comfort-package</b> 1_only in conjunction with Code 871, 889, 890 and P27, P59 or 950 <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	787,50
		○	○	○	○	○	0,00
P27	<b>Style</b> 1_only in conjunction with Code 101A, 311A, 371A or 372A. Code H61, 310 or 938, Code R78, R11, R30, R31, R55, 66R, 72R, 76R, RQT, RVG or RVK. Code L3E or L3B 2_not in conjunction with Code P59, 950 <b>i.V.m. Code PYB/PYD</b>	●	●	●	●	●	945,00
		○	○	○	○	○	0,00
P34	<b>Leather package</b> 1_only in conjunction with Code 401 or 873 and Code 201A, 205A, 211A and 950 or P59 2_not in conjunction with Code P39 <b>i.V.m. Code 950</b>	●	●	●	●	●	1459,50
		●	●	●	●	●	1050,00
P39	<b>AMG Leather package</b> 1_only in conjunction with Code 950, 401 or 873, Code 257A or 258A 2_not in conjunction with Code P27, P34 or P59 3_for certain countries only	●	●	●	●	●	1050,00
P44	<b>Parking package with reversing camera</b> 1_only in conjunction with Code 235 and 218 2_not in conjunction with Code P47 <b>i.V.m. Code PYA</b> <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	976,50
		●	●	●	●	●	624,75
		○	○	○	○	○	0,00
P47	<b>Parking Package with 360° camera</b> 1_only in conjunction with Code P27, P59 or 950, 234 or 23P and 235 and 501 2_not in conjunction with Code P44 <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	1407,00
		●	●	●	●	●	430,50
P49	<b>Mirror package</b> 1_only in conjunction with Code U62, 249, 500 <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	383,25
		○	○	○	○	○	0,00
P54	<b>Anti-Theft Protection package</b> 2_only in conjunction with Code P27, P59 or 950, 551 and 882 <b>i.V.m. Code 362</b>	●	●	●	●	●	430,50
		●	●	●	●	●	462,00
P55	<b>Night package</b> 1_only in conjunction with Code P59 or 950, Code 840 and 66R, R31, R55, R78, 72R, RQT, RVG or RVK <b>i.V.m. Code 950</b>	●	●	●	●	●	840,00
		●	●	●	●	●	409,50
P59	<b>Progressive</b>	-	-	●	-	-	1076,25
		●	●	-	●	●	1307,25

**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	247.003	247.012	247.014	247.084	247.087	
	1_only in conjunction with Code 101A, 105A, 201A, 205A, 211A, 321A or 381A. Code 2U5, H60, H15, H23 or H44, 310 or 938. Code L3E or L3B. Code 72R, R11, R31, R55, R78, 51R, 66R, 76R, RQT, RVG or RVK 2_not in conjunction with Code P27, 950 i.V.m. Code PYF	○	○	○	○	○	0,00
PAC	Vorteils-Paket	S	S	S	S	S	0,00
PAD	Engineering package 1_only in conjunction with Code U29, 459, 641 or 642, 23P, 889 2_for certain countries only	●	●	●	●	●	3108,00
PBF	Preinstallation for Connectivity package 2_not in conjunction with Code PBG 2_only in conjunction with Code 365 and 01U	●	●	●	●	●	682,50
	i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	0,00
PBG	Preinstallation for Navigation and Comfort Connectivity package 1_only in conjunction with Code 365, 01U, 02U, 12U 2_not in conjunction with Code PBF 3_for certain countries only	●	●	●	●	●	808,50
PBI	Preinstallation for Smartphone Connectivity package 1_only in conjunction with Code 08U, 09U, 14U 2_for certain countries only	●	●	●	●	●	420,00
PBP	ENERGIZING package 1_only in conjunction with Code P59 or 950 and 355, 853 or 810, 859, 877, 873 or 401 2_not in conjunction with Code PBR i.V.m. Code PYN/PYO	●	●	●	●	●	1470,00
PBR	ENERGIZING package Plus 1_in conjunction with Code P59 only in conjunction with Code 355, 409, 581, 873 or 401, 853 or 810, 859, 877 2_in conjunction with Code 950 only in conjunction with Code 355, 581, 873 or 401, 853 or 810, 859, 877 3_not in conjunction with Code PBP i.V.m. Code 7U4	●	●	●	●	●	2625,00
PYA	WEU Standard Equipment 1_for certain countries only	●	●	●	●	●	0,00
PYB	SE Package 1_for certain countries only	●	●	-	●	●	0,00
PYD	Style Line	●	●	-	●	●	960,00
	1_for certain countries only	-	-	●	-	-	0,00
PYF	Progressive Line	-	-	●	-	-	523,00
		●	-	-	-	-	1078,00
		-	-	-	-	●	1432,00
		-	●	-	●	-	1314,00
	1_for certain countries only						
PYH	AMG Line 1_for certain countries only	●	●	-	●	●	2868,00
		-	-	●	-	-	2312,00
PYM	Advantage Package 1_for certain countries only	●	●	●	●	●	1836,00
					●	●	1080,00
							1458,00
PYN	Premium Package 1_for certain countries only	●	●	●	●	●	3140,00
PYO	Premium Plus Package 1_for certain countries only	●	●	●	●	●	4706,00
U59	Seat comfort package 1_only in conjunction with Code 7U2 or 7U4	○	○	○	○	○	0,00
U62	Light and sight package 1_only in conjunction with Code B18 and 336	S	S	S	S	S	0,00
U63	Driving instruction vehicle, base specification 1_only in conjunction with Code P27, P59 or 950, 931, U00 2_not in conjunction with Code P55, 426, 429, 840, 877, 896, 897, 899, 965	●	●	-	●	●	572,25

**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

B Sportstourer					
	B 180 d	B 200 d	B 220 d	B 180	B 200
	247.003	247.012	247.014	247.084	247.087

Code	Designation						LLP
	3_for certain countries only <b>i.V.m. Code U64</b>	○	○	-	○	○	0,00
U90	Low-Line package China 1_only in conjunction with Code 830	-	-	-	-	○	0,00
U92	High-Line-package China 1_only in conjunction with Code 830	-	-	-	-	○	0,00
498	Japan specification	-	○	○	○	○	0,00
00B	Owner's Manual and Service Booklet - Danish	○	○	○	○	○	0,00
01B	Owner's Manual and Service Booklet - Dutch	○	○	○	○	○	0,00
01U	Preinstallation for Navigation Services 1_only in conjunction with Code 362, PBF or PBG 2_for certain countries only	○	○	○	○	○	0,00
02B	Owner's Manual and Service Booklet - German	○	○	○	○	○	0,00
02U	Preinstallation for Office in the car 1_only in conjunction with Code 362, PBG, 859 2_for certain countries only	○	○	○	○	○	0,00
03B	Owner's Manual and Service Booklet - Russian	○	○	○	○	○	0,00
04B	Owner's Manual and Service Booklet - Finnish	○	○	○	○	○	0,00
05B	Owner's Manual and Service Booklet - English	○	○	○	○	○	0,00
05Z	Run-on times MPM 4 hours 1_only in conjunction with Code 965 2_not in conjunction with Code 06Z 3_not valid, only for Code 017	○	○	U	U	U	0,00
06B	Owner's Manual and Service Booklet - Italian	○	○	○	○	○	0,00
06Z	Run-on times MPM w/o time limit 1_only in conjunction with Code 965 2_not in conjunction with Code 05Z 3_not valid, only for Code 017	○	○	U	U	U	0,00
07B	Owner's Manual and Service Booklet - French	○	○	○	○	○	0,00
08B	Owner's Manual and Service Booklet - Spanish	○	○	○	○	○	0,00
08U	Preinstallation for Vehicle Setup 1_only in conjunction with Code 09U, 362 2_only in conjunction with PBI or certain in countries <b>i.V.m. Code PBI</b>	●	●	●	●	●	52,50
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○	○	○	0,00
09U	Preinstallation for Vehicle Monitoring 1_only in conjunction with Code 08U, 362 2_only in conjunction with PBI or certain in countries <b>i.V.m. Code PBI</b>	●	●	●	●	●	52,50
10B	Owner's Manual and Service Booklet - Swedish	○	○	○	○	○	0,00
11B	Owner's Manual and Service Booklet - Arabic	○	○	○	○	○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	○	○	○	○	○	0,00
12U	Preinstallation for Concierge Service 1_only in conjunction with Code PBG in certain countries 2_for certain countries only	○	○	○	○	○	0,00
13B	Owner's Manual and Service Booklet - Norwegian	○	○	○	○	○	0,00
14B	Owner's Manual and Service Booklet - Greek	○	○	○	○	○	0,00
14U	Smartphone integration 1_only in conjunction with Code 16U, 17U 2_for certain countries only <b>i.V.m. Code PBI</b>	●	●	●	●	●	262,50
15B	Owner's Manual and Service Booklet - Turkish	○	○	○	○	○	0,00
15U	Pre-installation for Mercedes-Benz Link	S	S	S	S	S	0,00
16B	Owner's Manual and Service Booklet - Polish	○	○	○	○	○	0,00
16U	Apple CarPlay 1_only in conjunction with Code 14U	○	○	○	○	○	0,00
17B	Owner's Manual and Service Booklet - Czech	○	○	○	○	○	0,00
17U	Android Auto 1_only in conjunction with Code 14U	○	○	○	○	○	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	○	○	○	○	○	0,00
18U	Baidu Carlife 1_only in conjunction with Code 14U 2_for certain countries only	-	-	-	○	○	0,00
19B	Owner's Manual and Service Booklet - French S. Am.	○	○	○	○	○	0,00
1P0	Sonderpreis	○	○	○	○	○	0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.	○	○	○	○	○	0,00

Code	Designation						LLP
20U	<b>Pre-installation for car sharing</b> 1_only in conjunction with Code 362 2_for certain countries only <b>i.V.m. Code PYA</b>	●	●	●	●	●	52,50
213	<b>Direct-Steer system</b> 1_only in conjunction with Code 459, 486 or 677	○	○	○	○	○	0,00
218	<b>Reversing camera</b> 2_not in conjunction with Code 501 <b>i.V.m. Code P44</b> <b>i.V.m. Code PYA</b>	○	○	○	○	○	0,00
21B	<b>Owner's Manual and Service Booklet - Portug. S. Am.</b>	○	○	○	○	○	0,00
21U	<b>Dashcam</b> 1_only in conjunction with Code 859 and 365 2_for certain countries only	●	●	●	●	●	210,00
228	<b>Auxiliary heater</b> 1_for certain countries only in conjunction with Code B24 2_for certain countries only, nur für Linkslenker	●	●	●	●	●	1155,00
22B	<b>Owner's Manual and Service Booklet - Japanese</b>	○	○	○	○	○	0,00
231	<b>Garage door opener</b> 1_only in conjunction with Code P49 2_for certain countries only	●	●	●	●	●	157,50
232	<b>Garage door opener (frequency range 284-390 MHz)</b> 1_only in conjunction with Code P49 2_for certain countries only	●	●	●	●	●	236,25
233	<b>Active Distance Assist DISTRONIC</b> 1_only in conjunction with Code 23P, 266, 270, 273, 426 or 429 2_not in conjunction with Code 234, 440 3_for certain countries only	○	○	○	○	○	0,00
234	<b>Blind Spot Assist</b> 1_only in conjunction with Code P49 or 275, 270 and 273 2_not in conjunction with Code 233 3_for certain countries only <b>i.V.m. Code 22P</b>	○	○	○	○	○	0,00
235	<b>Active Parking Assist with PARKTRONIC</b> <b>i.V.m. Code P44/P47</b>	●	●	●	●	●	708,75
239	<b>Active Distance Assist DISTRONIC</b> 1_only in conjunction with Code 426 or 429 2_not in conjunction with Code 440 or L3A 3_Certain countries only	○	○	○	○	○	0,00
23B	<b>Owner's Manual and Service Booklet - simpl. Chinese</b>	○	○	○	○	○	0,00
241	<b>Front seat left, electrically adjustable memory switch</b> 1_only in conjunction with Code 275 and U22 or 409 2_not in conjunction with Code 7U1 3_Right-hand-drive vehicles only <b>i.V.m. Code PYO</b>	○	○	○	○	○	0,00
242	<b>Front pass. seat, electrically adj. with memory function</b> 1_only in conjunction with Code 275 and U22 or 409 2_not in conjunction with Code 842 or 7U1 3_only for Left Hand Drive <b>i.V.m. Code PYO</b>	○	○	○	○	○	0,00
243	<b>Active Lane Keeping Assist</b> 1_not in conjunction with Code 233 <b>i.V.m. Code 22P/51B</b>	○	○	○	○	○	0,00
249	<b>Interior mirror and driver's exterior mirror automatically dimming</b> 1_only in conjunction with Code P49	○	○	○	○	○	0,00
24B	<b>Owner's Manual and Service Booklet - trad. Chinese</b>	○	○	○	○	○	0,00
258	<b>Active Brake Assist</b> 1_only for certain countries; Serie in bestimmten Ländern 2_not in conjunction with Code 233 or 239	○	○	○	○	○	0,00
25B	<b>Owner's Manual and Service Booklet - Korean</b>	○	○	○	○	○	0,00
260	<b>Deletion of model plate on boot lid</b> 1_only for certain countries	○	○	○	○	○	0,00
263	<b>Number plate mounting for Asia / Mexico</b> 1_only for certain countries 2_not in conjunction with Code 968	○	○	○	○	○	0,00
266	<b>Active Steering Assist</b>	○	○	○	○	○	0,00

from **Price list B-Class**

27/11/2018 Launch MY 809+059, SR 03 Dec 2018

V3

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

Code	Designation	B Sportstourer					LLP
		247.003 B 180 d	247.012 B 200 d	247.014 B 220 d	247.084 B 180	247.087 B 200	
	1_only in conjunction with Code 233 2_for certain countries only						
26B	Owner's Manual and Service Booklet - Chinese Taiwan	○	○	○	○	○	0,00
26U	Preinstallation for engine remote start 1_only in conjunction with Code 08U 2_for certain countries only i.V.m. S-Code PZG	●	●	●	●	●	105,00 157,50
270	GPS aerial 1_only in conjunction with Code 233, 234, 344, 355, 362, 501, 899 or B24	○	○	○	○	○	0,00
273	Exit warning function	○	○	○	○	○	0,00
274	Telephone aerial 1_only in conjunction with Code 344, 501, 899 or B24	○	○	○	○	○	0,00
275	Driver's seat, electrically adjustable with memory function 1_only in conjunction with Code U22 or 409 and Code 7U2 or 7U4 i.V.m. Code PYO	●	●	●	●	●	362,25 0,00
286	Luggage net on driver's and front pass. backrest 1_only in conjunction with Code 7U2 or 7U4	○	○	○	○	○	0,00
287	Folding rear-seat backrests	S	S	S	S	S	0,00
293	Sidebags in rear 1_only in conjunction with Code 7U2 or 7U4	●	●	●	●	●	393,75
294	Kneebag 1_for certain countries only	○	○	○	○	○	0,00
299	PRE-SAFE® system 1_for certain countries only i.V.m. Code 23P	●	●	●	●	●	346,50 0,00
2R9	Winter (M+S) wheel and tyre assembly x 4 1_for certain countries only 2_only in conjunction with Code 651 or 652 3_not in conjunction with Code 950 or U29	●	●	●	●	●	1417,50
2U0	car2go pre-installation 1_only in conjunction with Code 355 or 859 2_not in conjunction with Code 865 3_for certain countries only	●	●	●	●	●	178,50
301	Ashtray insert for cup holder with cigarette lighter 1_for certain countries only	●	●	●	●	●	47,25
30B	Owner's Manual and Service Booklet - Slovenian	○	○	○	○	○	0,00
310	Twin cup holder 1_not in conjunction with Code 938 i.V.m. Code P27/P59/950 i.V.m. Code PYA	●	●	●	●	●	26,25 0,00 0,00
31B	Owner's Manual and Service Booklet - Hungarian	○	○	○	○	○	0,00
32B	Owner's Manual and Service Booklet - Bulgarian	○	○	○	○	○	0,00
333	Console for multi-point controls 1_only LHD 2_only in conjunction with Code 938 and 965 and 426 or 429 3_not in conjunction with Code 301, 310, 73B, 897, 899 4_not valid, only for Code 017	●	●	U	U	U	84,00
334	Preinstallation for two-way radio in glove compartment 1_Only in conjunction with Code 965 2_not in conjunction with Code 335 3_not valid, only for Code 017	●	●	U	U	U	63,00
335	Preinstallation for two-way radio in boot 1_only in conjunction with Code 965 2_not in conjunction with Code 334 3_not valid, only for Code 017	●	●	U	U	U	63,00
336	Preinstallation for taximeter 1_only in conjunction with Code 965 and 51U 2_not in conjunction with Code 882, B18 3_not valid, only for Code 017	●	●	U	U	U	57,75
337	Mirror taximeter 1_only in conjunction with Code 965 2_not in conjunction with Code 231 3_for certain countries only 4_not valid, only for Code 017	●	●	U	U	U	871,50
33B	Owner's Manual and Service Booklet - Romanian	○	○	○	○	○	0,00

**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

B Sportstourer				
B 180 d	B 200 d	B 220 d	B 180	B 200
247.003	247.012	247.014	247.084	247.087

Code	Designation						LLP
341	<b>Complete roof sign ex factory</b> 1_only in conjunction with Code 965 and 342 2_not in conjunction with Code 413 3_for certain countries only 4_not valid, only for Code 017	●	●	U	U	U	257,25
342	<b>Taxi roof sign connection</b> 1_only in conjunction with Code 965 2_not in conjunction with Code 413 3_for certain contries only 4_not valid, only for Code 017	●	●	U	U	U	73,50
344	<b>Pre-installation for aerial for taxi management systems</b> 1_only in conjunction with Code 270, 274 and 965 2_not in conjunction with Code B24, 356 3_not valid, only for Code 017	●	●	U	U	U	131,25
345	<b>Windscreen wiper with rain sensor</b>	S	S	S	S	S	0,00
34B	<b>Owner's Manual and Service Booklet - Croatian</b>	○	○	○	○	○	0,00
351	<b>Mercedes-Benz emergency call system</b> 1_only in conjunction with Code 362	○	○	○	○	○	0,00
355	<b>Extended MBUX functions</b> 1_only in conjunction with Code 548 or 549 and 270 and 446 2_for certain countries only <b>i.V.m. Code PYA</b>	●	●	●	●	●	472,50
		○	○	○	○	○	0,00
356	<b>Roof-mounted radio aerial</b> 1_only in conjunction with Code 965 2_not in conjunction with Code 344 3_not valid, only for Code 017	●	●	U	U	U	204,75
35B	<b>Owner's Manual and Service Booklet - Latvian</b>	○	○	○	○	○	0,00
362	<b>Communications module (LTE) for the use of Mercedes me connect services</b> 1_only in conjunction with Code 270 and 351 2_Standard in certain countries 3_for certain countries only	○	○	○	○	○	0,00
363	<b>ECALL - Transition to national emergency call</b> 2_only in conjunction with Code 351	○	○	○	○	○	0,00
365	<b>Hard-disc navigation</b> 1_only in conjunction with Code 355 <b>i.V.m. Code PBF/PBG</b> <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	577,50
		○	○	○	○	○	0,00
		○	○	○	○	○	0,00
367	<b>Preinstallation for Live Traffic Information</b> 1_only in conjunction with Code 355 and 362 2_for certain countries only	○	○	○	○	○	0,00
36B	<b>Owner's Manual and Service Booklet - Lithuanian</b>	○	○	○	○	○	0,00
37B	<b>Owner's Manual and Service Booklet - Slovakian</b>	○	○	○	○	○	0,00
38B	<b>Owner's Manual and Service Booklet - Estonian</b>	○	○	○	○	○	0,00
39B	<b>Owner's Manual and Service Booklet - Serbian</b>	○	○	○	○	○	0,00
3R1	<b>winter (M+S) wheel and tyre assembly x 4</b> 1_for certain countries only 2_only in conjunction with Code 651 or 652 3_not in conjunction with Code U29	●	●	-	●	●	1102,50
400	<b>Rear armrest</b>	S	S	S	S	S	0,00
401	<b>Climatised front seats</b> 1_only in conjunction with Code 101A, 105A, 159A, 201A, 205A, 211A, 257A or 258A 2_not in conjunction with Code 873 <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	934,50
		●	●	●	●	●	630,00
		●	●	●	●	●	630,00
409	<b>Multicontour seat package</b> 1_only in conjunction with Code 7U2 2_not in conjunction with Code U22, 311A, 321A, 371A, 372A or 381A <b>i.V.m. Code PBR</b>	●	●	●	●	●	619,50
		○	○	○	○	○	0,00
40B	<b>Owner's Manual and Service Booklet - ukrainian</b>	○	○	○	○	○	0,00
413	<b>Panoramic sliding sunroof</b> 1_not in conjunction with Code 342 <b>i.V.m. Code PYO</b>	●	●	●	●	●	1202,25
		○	○	○	○	○	0,00
41B	<b>Owner's Manual and Service Booklet - hebrew</b>	○	○	○	○	○	0,00
428	<b>Steering wheel shift paddles</b>	○	○	○	○	○	0,00



**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	247.003 B 180 d	247.012 B 200 d	247.014 B 220 d	247.084 B 180	247.087 B 200	
	1_only in conjunction with Code 426 or 429 and L3A, L3B or L3E						
42B	<b>Owner's Manual and Service Booklet - Indonesian</b>	○	○	○	○	○	0,00
43B	<b>Owner's Manual and Service Booklet - Thai</b>	○	○	○	○	○	0,00
440	<b>Cruise control</b> 1_not in conjunction with Code 233 or 239	S	S	S	S	S	0,00
443	<b>Heated multifunction steering wheel</b> 1_only in conjunction with Code 426 or 429 and L3B	●	●	●	●	●	351,75
	<b>i.V.m. Code P59</b>	●	●	●	●	●	168,00
446	<b>Touchpad without Controller</b> <b>i.V.m. Code PYA</b>	○	○	○	○	○	147,00 0,00
44B	<b>Owner's Manual and Service Booklet - Vietnamese</b>	○	○	○	○	○	0,00
450	<b>Taxi version, international</b> 1_only in conjunction with Code 965 and 334 or 335, 837, 301 or 336 or 337  2_only for Left Hand Drive 3_not valid, only for Code 017	●	●	U	U	U	945,00
458	<b>All-digital instrument display</b>  1_only in conjunction with Code 859 <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	472,50 225,00 360,00 0,00
459	<b>Suspension with Adaptive Damping system</b> 1_only in conjunction with Code 213 2_for certain countries only <b>i.V.m. Code 950 (ohne PYH)</b> <b>i.V.m. Code PAD</b>	●	●	●	●	●	1039,50 735,00 0,00
463	<b>Head-up Display</b> 1_only in conjunction with Code 355 or 859 and P59 or 950	●	●	●	●	●	1039,50
474	<b>Diesel particulate filter</b>	○	-	-	-	-	0,00
475	<b>Tyre pressure monitoring system</b> 1_Standard in certain countries <b>i.V.m. S-Code 6P5</b>	○	○	○	○	○	0,00
477	<b>Tyre pressure loss warning system</b> 1_for certain countries only	○	○	○	○	○	0,00
482	<b>Suspension with higher ground clearance</b> 1_not in conjunction with Code 950 2_for certain countries only	●	●	●	●	●	105,00
485	<b>Comfort suspension</b> 1_not in conjunction with Code 950	S	S	S	S	S	0,00
500	<b>Electrically folding exterior mirrors</b> 1_only in conjunction with Code P49	○	○	○	○	○	0,00
501	<b>360° camera</b> 1_only in conjunction with Code 270 and 274 2_in conjunction with Code P47 not in conjunction with Code 218	○	○	○	○	○	0,00
504	<b>Speed Limit Assist</b> 1_only in conjunction with Code 51B 2_not in conjunction with Code 513, 365 and 233	○	○	○	○	○	0,00
513	<b>Traffic Sign Assist</b> 1_only in conjunction with Code 365 2_not in conjunction with Code 504 3_for certain countries only	●	●	●	●	●	309,75
517	<b>HD digital radio standard</b> 1_for certain countries only	-	○	○	○	○	0,00
518	<b>Media Interface Cable kit</b> 1_for certain countries only	●	●	●	●	●	52,50
51B	<b>Rating, country group EURO-NCAP</b> 1_only in conjunction with Code 258 or 239, 243 or 233, 504 or 513 2_for certain countries only	○	○	○	○	○	0,00
51U	<b>Roof liner in black fabric</b>	○	○	○	○	○	0,00
524	<b>Transport protection</b> 1_only in conjunction with Code 662U 2_for certain countries only 3_not in conjunction with Code 820, 14P, 15P, 16P	●	●	●	●	●	168,00
537	<b>Digital radio</b> 1_only in conjunction with Code 79B 2_for certain countries only	●	●	●	●	●	210,00



**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	247.003 B 180 d	247.012 B 200 d	247.014 B 220 d	247.084 B 180	247.087 B 200	
539	Digital radio standard 1_for certain countries only	●	●	●	●	●	210,00
543	Sun visor with illuminated vanity mirror	S	S	S	S	S	0,00
545	MBUX multimedia system 1_not in conjunction with Code 355, 859, B63, PBF or PBG 2_for certain countries only	S	S	S	S	S	0,00
546	Active Speed Limit Assist 1_only in conjunction with Code 233 and 513 2_for certain countries only	○	○	○	○	○	0,00
547	MBUX multimedia system 1_only in conjunction with Code 859 2_not in conjunction with Code 355 3_for certain countries only	○	○	○	○	○	0,00
548	MBUX multimedia system 1_only in conjunction with Code 355 or 2U0 2_not in conjunction with Code 859 3_for certain countries only	○	○	○	○	○	0,00
549	MBUX multimedia system 1_only in conjunction with Code 355 and 859	○	○	○	○	○	0,00
550	Trailer coupling with ESP® trailer stabilisation 1_not in conjunction with Code Z97 2_for certain countries only	●	●	●	●	●	840,00
551	Anti-theft alarm system (ATA) 1_scope of delivery of Code P54 in certain countries 2_for certain countries only i.V.m. Code P54	●	●	●	●	●	262,50
552	Anti-theft alarm system (ATA) 2_for certain countries only 2_only in conjunction with Code P54	○	○	○	○	○	0,00
580	THERMATIC automatic climate control 1_not in conjunction with Code PBR	○	○	○	○	○	0,00
581	THERMOTRONIC automatic climate control i.V.m. Code PBR i.V.m. Code PYF/PYH	●	●	●	●	●	535,50
58U	Roof liner in crystal grey fabric 1_not in conjunction with Code 371A, 105A, 205A oder 159A	○	○	○	○	○	0,00
598	Petrol particulate filter 1_for certain countries only, only in conjunction with Code 927	-	-	-	○	○	0,00
5U3	AIRPANEL 1_for certain countries only	●	-	-	●	●	84,00
608	Adaptive Highbeam Assist 1_only in conjunction with Code 631 or 632 2_not in conjunction with Code 628 3_for certain countries only i.V.m. Code 640	●	●	●	●	●	189,00
613	Halogen headlamps for left-hand traffic including integral LED daytime running lamps 1_not in conjunction with Code PAD 2_for certain countries only	○	○	○	○	○	0,00
620	Halogen headlamps including integral LED daytime running lamps 1_not in conjunction with Code PAD 2_for certain countries only	○	○	○	○	○	0,00
623	Gulf States specification	-	●	●	●	●	157,50
625	Australia specification	○	○	○	○	○	0,00
628	Adaptive Highbeam Assist Plus 1_only in conjunction with Code 641 or 642 2_not in conjunction with Code 608	○	○	○	○	○	0,00
631	LED High Performance headlamp 1_not in conjunction with Code PAD 2_for certain countries only i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	871,50
632	LED High Performance headlamp 1_not in conjunction with Code PAD 2_only for certain countries i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	871,50
634	Omission of first-aid kit	○	○	○	○	○	0,00

from

## Price list B-Class

27/11/2018

Launch MY 809+059, SR 03 Dec 2018

V3

● available at extra charge    ○ available at no extra charge    U annotations existing  
 S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	247.003 B 180 d	247.012 B 200 d	247.014 B 220 d	247.084 B 180	247.087 B 200	
	1_not in conjunction with Code 820 2_for certain countries only						
636	Omission of hazard warning triangle 1_not in conjunction with Code 820 2_for certain countries only	○	○	○	○	○	0,00
641	MULTIBEAM LED 1_only in conjunction with Code 628 2_for certain countries only	●	●	●	●	●	1312,50
	i.V.m. Code PAD	○	○	○	○	○	0,00
	i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	441,00
	i.V.m. Code PYO	○	○	○	○	○	0,00
642	MULTIBEAM LED 1_only in conjunction with Code 628 2_for certain countries only	●	●	●	●	●	1312,50
	i.V.m. Code PAD	○	○	○	○	○	0,00
	i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	441,00
	i.V.m. Code PYO	○	○	○	○	○	0,00
643	43.2 cm (17-inch) steel wheels with wheel trims 1_only in conjunction with Code R01 2_not in conjunction with Code U29, 950, R66 3_for certain countries only	- ●	- ●	S -	- ●	- ●	0,00 315,00
	i.V.m. Code P59	○	○	-	○	○	0,00
645	M+S winter tyres, set of 4 1_only in conjunction with Code R78, 72R, RVG	●	●	●	●	●	115,50
651	Winter complete wheels fitted 1_for certain countries only 2_only in conjunction with Code 3R1, 2R9, 8R5 or 8R2	○	○	○	○	○	0,00
652	Summer complete tyres fitted 1_for certain countries only 2_only in conjunction with Code 3R1, 2R9, 8R5 oder 8R2	○	○	○	○	○	0,00
666	Freight packaging without tie-down hooks 1_not in conjunction with Code 820 2_for certain countries only	●	●	●	●	●	26,25
	i.V.m. Code 14P/15P/16P	○	○	○	○	○	0,00
668	Freight packaging with tie-down hooks 1_not in conjunction with Code 820 2_for certain countries only	●	●	●	●	●	26,25
66R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels 1_only in conjunction with Code R1A, R01 or R03 2_not in conjunction with Code 950 3_in conjunction with Code R03 and R1A Code R66 is not possible	- ●	- ●	● -	- ●	- ●	1312,50 1627,50
	i.V.m. Code P27	●	●	-	●	●	1155,00
	i.V.m. Code P55	-	-	●	-	-	840,00
	i.V.m. Code P59	○	○	○	○	○	0,00
		●	●	●	●	●	840,00
677	Lowered comfort suspension 1_only in conjunction with Code 213 2_for certain countries only	●	●	●	●	●	304,50
	i.V.m. Code 950	○	○	○	○	○	0,00
682	Fire extinguisher 1_for certain countries only	●	●	●	●	●	0,00
687	Model year on model plate	○	○	○	○	○	0,00
690	Collapsible spare wheel 1_only in conjunction with Code B12 2_for certain countries only, for certain countries not in conjunction with Code R66	-	○	○	○	○	0,00
70B	Fluorescent jacket for driver 1_for certain countries only 2_not in conjunction with Code 71B	●	●	●	●	●	5,25
71B	Fluorescent jackets for driver and passengers 1_for certain countries only 2_not in conjunction with Code 70B	●	●	●	●	●	26,25
72R	43.2 cm (17-inch) 10-spoke light-alloy wheels	- ●	- ●	● -	- ●	- ●	472,50 787,50

**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	B 180 d 247.003	B 200 d 247.012	B 220 d 247.014	B 180 247.084	B 200 247.087	
	1_only in conjunction with Code R01 or 645 2_not in conjunction with Code 950, U29, R66 3_for certain countries only <b>i.V.m. Code P27</b>	-	-	○	-	-	0,00
	<b>i.V.m. Code P59</b>	●	●	○	●	●	315,00
		○	○	○	○	○	0,00
<b>73B</b>	<b>Stowage compartment in centre console, with retractable cover</b> 1_only in conjunction with Code 426 or 429 2_for certain countries only	●	●	●	●	●	0,00
<b>762</b>	<b>Radio remote control without panic button</b> 1_for certain countries only	○	○	○	○	○	0,00
<b>763</b>	<b>Radio remote control with panic switch</b> 1_only in conjunction with Code 551 and certain countries only	-	○	○	○	○	0,00
<b>76R</b>	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b>  1_only in conjunction with Code R01 2_not in conjunction with Code R66, U29 or 950 <b>i.V.m. Code P27</b>	-	-	●	-	-	472,50
		●	●	-	●	●	787,50
	<b>i.V.m. Code P59</b>	-	-	○	-	-	0,00
	<b>i.V.m. Code PYD</b>	●	●	-	●	●	315,00
		○	○	○	○	○	0,00
		○	○	○	○	○	0,00
<b>772</b>	<b>AMG bodystyling</b> 1_only in conjunction with Code 950	○	○	○	○	○	0,00
<b>79B</b>	<b>Preinstallation for digital radio</b> 1_in certain countries only in conjunction with Code 362 2_in certain countries only in conjunction with Code 537 3_in conjunction with Code 835 with Code 355, 859, 362	○	○	○	○	○	0,00
<b>7U1</b>	<b>Manually adjustable front seats</b> 1_only in conjunction with Code 301A 2_not in conjunction with Code 7U2, 7U4	○	○	○	○	○	0,00
<b>7U2</b>	<b>Luxury seats</b> 1_only in conjunction with Code 101A, 105A, 201A, 205A, 311A, 321A, 371A, 372A or 381A and U59 and 286 2_not in conjunction with Code 7U1, 7U4	○	○	○	○	○	0,00
<b>7U4</b>	<b>Sports seats</b> 1_only in conjunction with Code 159A, 211A, 257A, 258A or 651A and Code U59 and 286 2_not in conjunction with Code 7U1, 7U2 <b>i.V.m. Code 950</b>	●	●	●	●	●	246,75
		○	○	○	○	○	0,00
<b>809</b>	<b>Technical modifications</b>	○	○	○	○	○	0,00
<b>810</b>	<b>Burmester® surround sound system</b> 1_only in conjunction with Code 355 or 859 2_not in conjunction with Code 965, Z97 3_for certain countries only <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	698,25
		●	●	●	●	●	435,75
		●	●	●	●	●	435,75
<b>820</b>	<b>Tourist vehicle</b> 1_not in conjunction with Code 634 or 636 2_for certain countries only	○	○	○	○	○	0,00
<b>821</b>	<b>Country code Brazil</b>	-	-	-	○	○	0,00
<b>822</b>	<b>South Africa specification</b>	○	○	○	○	○	0,00
<b>823</b>	<b>country code Switzerland</b>	○	○	○	○	○	0,00
<b>824</b>	<b>Additional parts for cold countries (engine air intake screen)</b> 2_for certain countries only	○	○	○	○	○	0,00
<b>829</b>	<b>Taiwan version</b>	○	○	○	○	○	0,00
<b>830</b>	<b>China specification</b>	-	-	-	○	○	0,00
<b>831</b>	<b>country code Italia</b>	○	○	○	○	○	0,00
<b>837</b>	<b>Taxi rubber floor mat</b> 1_only in conjunction with Code 965 2_not in conjunction with Code U40 3_not valid, only for Code 017 <b>i.V.m. Code 450</b>	●	●	U	U	U	189,00
		○	○	○	○	○	0,00
<b>840</b>	<b>Heat-insulating dark-tinted glass</b> 1_only in conjunction with Code P27, P59 or 950 2_not in conjunction with Code U63, 632 3_for certain countries only	●	●	●	●	●	315,00

Code	Designation						LLP
	<b>i.V.m. Code P55</b>	○	○	○	○	○	<b>0,00</b>
<b>853</b>	<b>Advanced Sound System</b> 1_for certain countries only <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	<b>262,50</b>
		○	○	○	○	○	<b>0,00</b>
		○	○	○	○	○	<b>0,00</b>
<b>859</b>	<b>Media-Display</b> 1_only in conjunction with Code 547 or 549 and 446 2_not in conjunction with Code 362 (f. c. countries), 835, 355, 79B, 537 <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	<b>682,50</b>
		○	○	○	○	○	<b>0,00</b>
		○	○	○	○	○	<b>0,00</b>
<b>862</b>	<b>Pre-installation for digital TV Japan</b> 1_only in conjunction with Code 355 and 859 2_for certain countries only	●	●	●	●	●	<b>94,50</b>
<b>865</b>	<b>TV tuner Japan</b> 1_only in conjunction with Code 355 and 859 2_for certain countries only	-	●	●	●	●	<b>945,00</b>
<b>871</b>	<b>HANDS-FREE ACCESS</b> 1_only in conjunction with Code P17	○	○	○	○	○	<b>0,00</b>
<b>873</b>	<b>Heated front seats</b> 1_not in conjunction with Code 401 <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	<b>304,50</b>
		○	○	○	○	○	<b>0,00</b>
		○	○	○	○	○	<b>0,00</b>
<b>875</b>	<b>Heated windscreen washer system</b>	●	●	●	●	●	<b>120,75</b>
<b>877</b>	<b>Ambient lighting</b> 1_only in conjunction with Code P59 or 950 2_not in conjunction with Code U63 <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	<b>278,25</b>
		○	○	○	○	○	<b>0,00</b>
		○	○	○	○	○	<b>0,00</b>
<b>882</b>	<b>Interior monitoring system</b> 1_only in conjunction with Code P54 2_not in conjunction with Code 336 3_for certain countries only	○	○	○	○	○	<b>0,00</b>
<b>885</b>	<b>Increased anti-theft protection</b> 1_for certain countries only	○	○	○	○	○	<b>0,00</b>
<b>889</b>	<b>KEYLESS-GO</b> 1_only in conjunction with Code P27, P59 or 950 <b>i.V.m. Code PAD/P17</b>	●	●	●	●	●	<b>420,00</b>
		○	○	○	○	○	<b>0,00</b>
<b>890</b>	<b>EASY-PACK tailgate</b> <b>i.V.m. Code P17</b> <b>i.V.m. Code PYB/PYD/PYF/PYH</b>	●	●	●	●	●	<b>409,50</b>
		○	○	○	○	○	<b>0,00</b>
		○	○	○	○	○	<b>0,00</b>
<b>896</b>	<b>Preinstallation for Digital vehicle key for smartphone</b> 1_only in conjunction with Code 897 or 899 and 362 2_for certain countries only	●	●	●	●	●	<b>105,00</b>
<b>897</b>	<b>Wireless charging and connection via Bluetooth</b> 1_only in conjunction with Code P29, P59 or 950 2_not in conjunction with Code 899 3_for certain countries only	●	●	●	●	●	<b>210,00</b>
<b>899</b>	<b>Multifunction telephony</b> 1_only in conjunction with Code P27, P59 or 950 and 270, 274 2_not in conjunction with Code 897 3_for certain countries only	●	●	●	●	●	<b>514,50</b>
<b>8R2</b>	<b>Complete winter (M+S) wheel-and-tyre assembly x 4, 19-inch, light-alloy</b>  1_only in conjunction with Code 651 or 652 2_for certain countries only	●	●	●	●	●	<b>2467,50</b>
<b>8R5</b>	<b>Complete winter wheel - AMG spoked design, 18"</b> 1_only in conjunction with Code 651 or 652 2_for certain countries only	●	●	●	●	●	<b>2205,00</b>
<b>913</b>	<b>Air conditioning preinstallation for hot countries</b> 1_for certain countries only	○	○	○	-	-	<b>0,00</b>
<b>916</b>	<b>Fuel tank with increased capacity</b>  <b>i.V.m. Code PYD/PYH/PYF</b>	-	-	●	-	-	<b>52,50</b>
		-	-	○	-	-	<b>0,00</b>
<b>922</b>	<b>Reduced output engines</b> 1_for certain countries only	-	-	-	-	○	<b>0,00</b>
<b>926</b>	<b>Emission control system with EU4 technology</b>	-	○	○	○	○	<b>0,00</b>

Code	Designation						LLP
	1_for certain countries only						
927	<b>EU6 emissions standard</b> 1_for certain countries only	○	○	○	○	○	0,00
928	<b>EU5 emission standard</b> 1_for certain countries only	-	-	-	○	○	0,00
931	<b>Additional interior mirror</b> 1_only in conjunction with Code U63 2_for certain countries only 3_not valid, only for Code 017	○	○	-	○	○	0,00
934	<b>Taxi/hire car emergency alarm system</b> 1_only in conjunction with Code 965, 942 and U32 2_for certain countries only 3_not valid, only for Code 017	●	●	○	○	○	257,25
936	<b>Cylinder cut-off</b> 1_for certain countries only	-	-	-	○	○	0,00
938	<b>Hands-free system</b> 1_only in conjunction with Code 965 and 426 or 429 2_not in conjunction with Code 301, 310, 73B 3_for certain countries only 4_not valid, only for Code 017	●	●	○	○	○	136,50
942	<b>Load compartment package</b> 1_only in conjunction with Code U35 2_for certain countries only <b>i.V.m. Code PYA</b>	●	●	●	●	●	141,75
945	<b>Emission control system China</b> 1_for certain countries only	-	-	-	○	○	0,00
961	<b>Petrol particulate filter</b> 1_only in conjunction with Code 927 2_for certain countries only	-	-	-	○	○	0,00
965	<b>Taxi and hire car</b> 1_only in conjunction with Code 7U2, P27 or P59, 101A or 105A, 233, 239 or 258 2_not in conjunction with Code U63, 2U0, 413, 810 3_for certain countries only 4_not valid, only for Code 017	●	●	○	○	○	577,50
968	<b>COC document EU6 without registration certificate part II</b> 1_only in conjunction with Code 927, 351, 2U8, 998 2_not in conjunction with Code 263 or 264 3_for certain countries only	○	○	○	○	○	0,00
969	<b>COC document EU6 with registration certificate part II</b> 1_only in conjunction with Code 927, 2U8, 998 2_for certain countries only	○	○	○	○	○	0,00
971	<b>Exhaust system with DPF Generation 1.5</b>	-	○	○	-	-	0,00
973	<b>Designation as owner-driver rental vehicle</b>	○	○	○	○	○	0,00
981	<b>Omission of vehicle registration document</b> 1_for certain countries only	○	○	○	○	○	0,00
986	<b>Identification label with VIN number</b> 1_for certain countries only	○	○	○	○	○	0,00
989	<b>Identification label under windshield</b> 1_for certain countries only	○	○	○	○	○	0,00
997	<b>Exhibition vehicle</b> 1_only for certain countries	○	○	○	○	○	0,00
B08	<b>Fanfare horn Asia</b> 1_for certain countries only	○	○	○	○	○	0,00
B12	<b>Tyre-change toolkit</b> 1_only in conjunction with Code 669, 690 or 623 2_for certain countries only	●	●	●	●	●	31,50
B18	<b>Spectacles compartment for driver</b> 1_not in conjunction with Code 336	S	S	S	S	S	0,00
B24	<b>Remote control for auxiliary heater</b> 1_only in conjunction with Code 228 and 362 (only for certain countries) 2_for certain countries only	●	●	●	●	●	210,00
B51	<b>TIREFIT</b> 1_for certain countries only 2_not in conjunction with Code R66 (for certain countries only) <b>i.V.m. Code PYA</b>	●	●	●	●	●	52,50
		○	○	○	○	○	0,00

from

## Price list B-Class

27/11/2018

Launch MY 809+059, SR 03 Dec 2018

V3

● available at extra charge    ○ available at no extra charge    U annotations existing  
 S standard equipment    - not available

B Sportstourer					
B 180 d	B 200 d	B 220 d	B 180	B 200	
247.003	247.012	247.014	247.084	247.087	

Code	Designation						LLP
B59	<b>DYNAMIC SELECT</b>	S	S	S	S	S	0,00
B63	<b>Sporty engine sound</b>	-	○	○	-	○	0,00
	1_only in conjunction with Code 950, 255 or 859						
H15	<b>wood linden black open-pored trim</b>	●	●	●	●	●	273,00
	1_only in conjunction with Code P50 or 950						
H23	<b>Brown open-pore walnut wood trim</b>	●	●	●	●	●	273,00
	1_only in conjunction with Code P34 or P59						
H44	<b>Light longitudinal-grain aluminium trim</b>	●	●	●	●	●	157,50
	1_only in conjunction with Code P59 or 950						
H59	<b>Carbon-fibre-look trim</b>	S	S	S	S	S	0,00
	1_not in conjunction with Code P27, P59, 950, 877						
H60	<b>Spiral-look trim elements</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code P59						
H61	<b>Ellipse-look trim</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code P27						
	2_not in conjunction with Code 877						
H62	<b>Carbon-structure trim</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 950						
K32	<b>Active Lane Change Assist</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 266 and 365						
	2_for certain countries only						
K33	<b>Extended automatic Re-start in traffic jams</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 233, 235 and 365						
	2_for certain countries only						
K34	<b>Route-based speed adaptation</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 233 and 365						
	2_for certain countries only						
L3A	<b>Multifunction sports steering wheel</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 426 or 429 and 428 or 411						
	2_not in conjunction with Code P27, P59, 950, 233, 239, 443						
L3B	<b>Multifunction sports steering wheel in nappa leather</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 443 and 426 or 429 and 428						
	2_not in conjunction with Code 950						
L3E	<b>Leather multifunction sports steering wheel</b>	●	●	●	●	●	183,75
	1_only in conjunction with Code 426 or 429 and 428 or 411						
	2_not in conjunction with Code 443 or 950						
	<b>i.V.m. Code P27/P59</b>	○	○	○	○	○	0,00
L5C	<b>Multifunction sports steering wheel in nappa leather</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 950, 426 or 429 and 431 or 411						
	2_not in conjunction with Code 443						
L5I	<b>Multifunction sports steering wheel in nappa leather / microfibre DINAMICA</b>	●	●	●	●	●	241,50
	1_only in conjunction with Code 950 and 426 or 429 and 431						
	2_not in conjunction with Code 443						
R00	<b>40.6 cm (16-inch) steel wheels with 10-hole trim</b>	S	S	-	S	S	0,00
	1_only in conjunction with Code R01 or R05						
	2_not in conjunction with Code U29, R66, 950						
	3_for certain countries only						
R01	<b>Summer tyres</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code R00, R30, R78 (f. c. countries), 643, 72R, 76R, R11, 66R, R31, R55, RVG, RVK, RQS oder RQT						
	3_for certain countries only						
R03	<b>Sports tyres</b>	○	○	○	○	○	0,00
	1_only in conjunction with Code 66R, R31, RQS or RQT						
	2_not in conjunction with Code R66						
R05	<b>Summer tyres</b>	○	○	-	○	○	0,00
	1_for certain countries only						
	1_only in conjunction with Code R00, R30 or R78						
R11	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b>	-	-	●	-	-	682,50
		●	●	-	●	●	997,50
	1_only in conjunction with Code R01						
	2_not in conjunction with Code R66, U29, 950						
	<b>i.V.m. Code P27</b>	-	-	●	-	-	210,00
		●	●	-	●	●	525,00
	<b>i.V.m. Code P55</b>	○	○	○	○	○	0,00
	<b>i.V.m. Code P59</b>	●	●	●	●	●	210,00

from

## Price list B-Class

27/11/2018

Launch MY 809+059, SR 03 Dec 2018

V3

● available at extra charge    ○ available at no extra charge    U annotations existing  
 S standard equipment    - not available

		B Sportstourer					LLP
Code	Designation	247.003	247.012	247.014	247.084	247.087	
R1A	<b>Sports tyres</b> 1_only in conjunction with Code 66R, R31, RQS or RQT 2_not in conjunction with Code R66 3_for certain countries only	○	○	○	○	○	0,00
R30	<b>40.6 cm (16") multi-spoke light-alloy wheels</b> 1_only in conjunction with Code R01 or R05 2_not in conjunction with Code U29, R66, 950 3_for certain countries only <b>i.V.m. Code P27</b> <b>i.V.m. Code P59</b>	●	●	-	●	●	682,50
		●	●	-	●	●	210,00
		○	○	-	○	○	0,00
R31	<b>45.7 cm (18") 5-twin-spoke light-alloy wheels</b>  1_only in conjunction with Code R01, R03 or R1A 2_not in conjunction with Code 950 3_in conjunction with Code R03 and R1A Code R66 is not possible 4_for certain countries only <b>i.V.m. Code P27</b>	-	-	●	-	-	1312,50
		●	●	-	●	●	1627,50
		●	●	-	●	●	1155,00
		-	-	●	-	-	840,00
	<b>i.V.m. Code P55</b>	○	○	○	○	○	0,00
	<b>i.V.m. Code P59</b>	●	●	●	●	●	840,00
R55	<b>48.3 cm (19-inch) 5-twin-spoke light-alloy wheels</b>  1_only in conjunction with Code R01 2_not in conjunction with Code R66, 482, 950 3_for certain countries only <b>i.V.m. Code P27</b>	-	-	●	-	-	1785,00
		●	●	-	●	●	2100,00
		-	-	●	-	-	1312,50
		●	●	-	●	●	1627,50
	<b>i.V.m. Code P55</b>	●	●	●	●	●	472,50
	<b>i.V.m. Code P59</b>	●	●	●	●	●	1312,50
R66	<b>Run-flat tyres</b> 1_only in conjunction with Code R01 and Code 643, 72R, 76R, R11, 66R, R31, RQS, RQT 2_for certain countries only	●	●	●	●	●	231,00
R78	<b>40.6 cm (16-inch) 5-twin-spoke light-alloy wheels</b> 1_only in conjunction with Code R01, R04 or 645 2_not in conjunction with Code 950, U29, R66 <b>i.V.m. Code P27/P59</b>	●	●	-	●	●	472,50
		○	○	-	○	○	0,00
RQS	<b>45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels</b> 1_only in conjunction with Code 950, R01, R03 or R1A 2_not in conjunction with Code P55 3_in conjunction with Code R03 and R1A Code R66 is not possible	○	○	○	○	○	0,00
RQT	<b>45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels</b>  1_only in conjunction with Code R01, R03 or R1A 2_in conjunction with Code R03 and R1A Code R66 is not possible <b>i.V.m. Code 950</b> <b>i.V.m. Code P27</b>	-	-	●	-	-	1785,00
		●	●	-	●	●	2100,00
		●	●	●	●	●	210,00
		-	-	●	-	-	1312,50
		●	●	-	●	●	1627,50
	<b>i.V.m. Code P55</b>	●	●	●	●	●	472,50
	<b>i.V.m. Code P55+950</b>	○	○	○	○	○	0,00
	<b>i.V.m. Code P59</b>	●	●	●	●	●	1312,50
RVG	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels</b>  1_only in conjunction with Code R01 or 645 2_not in conjunction with Code R66, 482 3_for certain countries only <b>i.V.m. Code 950</b> <b>i.V.m. Code P27</b>	-	-	●	-	-	2047,50
		●	●	-	●	●	2362,50
		●	●	●	●	●	630,00
		-	-	●	-	-	1575,00
		●	●	-	●	●	1890,00
	<b>i.V.m. Code P55+P59</b>	●	●	●	●	●	735,00
	<b>i.V.m. Code P59</b>	●	●	●	●	●	1575,00
RVK	<b>AMG multi-spoke wheels, 19", with mixed-size tyres</b>  1_only in conjunction with Code R01 2_not in conjunction with Code R66, 482 3_for certain countries only	-	-	●	-	-	2415,00
		●	●	-	●	●	2730,00



**from Price list B-Class**
**27/11/2018 Launch MY 809+059, SR 03 Dec 2018**
**V3**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		B Sportstourer						LLP
Code	Designation	247.003	247.012	247.014	247.084	247.087		
	i.V.m. Code 950	●	●	●	●	●		997,50
	i.V.m. Code P27	-	-	●	-	-		1942,50
	i.V.m. Code P55+P59	●	●	-	●	●		2257,50
	i.V.m. Code P59	●	●	●	●	●		1102,50
		●	●	●	●	●		1942,50
U00	<b>Velour floor mats for driving instruction vehicles</b> 1_only in conjunction with Code U63 2_LHD only	○	○	-	○	○		0,00
U01	<b>Status display for rear seat belts in instrument cluster</b> 1_for certain countries only	○	○	○	○	○		0,00
U10	<b>Automatic deactivation of front passenger airbag</b> 1_for certain countries only i.V.m. Code 51B	●	●	●	●	●		99,75
		○	○	○	○	○		0,00
U12	<b>Velour floor mats</b> 1_not in conjunction with Code 950 2_for certain countries only i.V.m. Code PYA	●	●	●	●	●		84,00
		○	○	○	○	○		0,00
U19	<b>MBUX augmented reality for navigation</b> 1_only in conjunction with Code 365 and 859 2_for certain countries only	●	●	●	●	●		262,50
U22	<b>4-way lumbar support</b> 1_only in conjunction with Code U59 2_not in conjunction with Code 409 3_for certain countries only i.V.m. Code PYO	●	●	●	●	●		162,75
		○	○	○	○	○		0,00
U25	<b>Illuminated door sill panels with "Mercedes-Benz" lettering</b> 1_only in conjunction with Code U62 2_for certain countries only i.V.m. Code PYN/PYO	●	●	●	●	●		157,50
		○	○	○	○	○		0,00
U26	<b>AMG floor mats</b> 1_only in conjunction with Code 950 2_for certain countries only	○	○	○	○	○		0,00
U29	<b>Braking system with larger brake discs on the front axle</b> 1_only in conjunction with Code PAD	○	○	○	○	○		0,00
U32	<b>Two additional master keys</b> 1_only in conjunction with Code 934 2_not valid, only for Code 017	●	●	U	U	U		157,50
				★	★	★		
U35	<b>Socket in load compartment</b> 1_only in conjunction with Code 942	○	○	○	○	○		0,00
U40	<b>Partition net</b> 1_not in conjunction with Code 837 2_for certain countries only	●	●	●	●	●		157,50
U41	<b>Water separator and lubrication package</b> 1_only in conjunction with Code 927 2_for certain countries only	-	○	○	-	-		0,00
U54	<b>Torsion-beam axle</b> 1_not in conjunction with Code 459	S	○	-	○	○		0,00
U55	<b>Multi-link axle</b>  1_for certain countries only and in conjunction with Code 66R, R31, R55, RQS, RQT, RVG, RVK 2_not in conjunction with Code 459	S	S	S	S	S		0,00
U64	<b>Driving instruction vehicle, full specification</b> 1_in conjunction with Code U63	●	●	-	●	●		1260,00
U65	<b>Additional exterior mirrors</b> 1_only in conjunction with Code U63	●	●	●	●	●		126,00
U67	<b>230 V socket in the rear</b>	●	●	●	●	●		120,75
U79	<b>BlueTEC diesel emission control system including AdBlue® reservoir</b>	○	○	○	-	-		0,00
Z83	<b>Activation of Hill-Start Assist</b> 1_only in conjunction with Code U64	○	○	○	○	○		0,00
Z97	<b>Electronic interface for remote control</b> Not in conjunction with Code 810, 550, 554, 965, Z90	●	●	●	●	●		399,00