

20/8/2018 Optional extras for the GLA

Valid from 08.10.2018 CY (809+059)

● available at extra charge ○ available at no extra charge U annotations existing  
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

		GLA										LLP
Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.947	
		GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	GLA 250 4MATIC Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 200 Sport Utility Vehicle RHD	
DB1	<b>Progressive Plus Auto package</b> National Package Included: 429-P49-P59-218-14U - 191U/589U/149U/696U/775U/787U/890U/990U/667U						●					1888,00
DB2	<b>Progressive Plus package</b> National Package Included: P49-P59-218-14U-175U/ 191U/589U/149U/696U/761U/787U/890U/895U/990U/667U						●					1149,00
DB3	<b>Offroad Auto package</b> National Package Included: 429-P27-P49-218-30P-14U-400-482-175U/191U/589U/149U/696U/761U/787U/890U/895U/990U/667U						●					1882,00
DB4	<b>Offroad package</b> National Package Included: P27-P49-218-30P-14U-400-482-175U/191U/589U/149U/696U/761U/787U/890U/895U/990U						U					1142,00
DB5	<b>Sport package</b> National Package Included: 950-218-14U-P49-857						●					2760,00
DB6	<b>White Art Plus</b> National Package Included: PEK 950-P49-P55-218-429-632						U					6144,00
DC1	<b>Advanced Plus Package</b> National Package Included: 429-P49-P59-218-14U-632 - 191U/589U/149U/696U/775U/787U/890U/990U/667U				●		●					3166,00
DC2	<b>Advanced Package</b> National Package Included: P49-P59-218-14U-632 - 191U/589U/149U/696U/775U/787U/890U/990U/667U					●						1750,00
DC3	<b>Entry Package</b> National Package Included: 218-14U - 191U/589U/149U/696U/775U/787U/890U/990U/667U					●						490,00
L	Left-hand drive	○	○	○	○	○	○	○	○	○	○	0,00
R	Right-hand drive	●	●	●	●	●	●	●	●	●	●	1113,00
000U	paintwork not yet finalised only in conjunction with code Z98	○	○	○	○	○	○	○	○	○	○	0,00
149U	polar white	○	○	○	○	○	○	○	○	○	○	0,00
191U	cosmos black metallic	●	●	●	●	●	●	●	●	●	●	619,50
589U	jupiter red	○	○	○	○	○	○	○	○	○	○	0,00
662U	designo mountain grey magno	●	●	●	●	●	●	●	●	●	●	1837,50
667U	denim blue metallic	●	●	●	●	●	●	●	●	●	●	619,50
696U	night black	○	○	○	○	○	○	○	○	○	○	0,00
775U	iridium silver metallic	●	●	●	●	●	●	●	●	●	●	619,50
787U	mountain grey metallic	●	●	●	●	●	●	●	●	●	●	619,50
890U	cavansite blue metallic - RUN OUT 10/18	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	619,50
896U	brilliant blue metallic certain countries only	-	-	-	-	●	-	●	-	↓	↓	619,50
990U	orient brown metallic - RUN OUT 10/18	↓	↓	↓	↓	↓	↓	↓	↓	↓	↓	619,50
992U	selenite grey metallic certain countries only	●	●	●	●	●	●	●	-	●	●	619,50
996U	designo hyacinth red metallic certain countries only	●	●	●	●	●	●	●	-	●	●	1837,50
021A	Coati fabric black certain countries only not in conjunction with code 950, P27, P34, P59	○	○	○	○	○	○	○	○	-	○	0,00
105A	ARTICO man-made leather sahara beige not in conjunction with code P34 or 950 only in conjunction with code P27 or P59 only in conjunction with code U59 in conjunction with Code P27 oder P59	●	●	●	●	●	●	●	-	●	●	273,00
111A	ARTICO man-made leather black not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59	●	●	●	●	●	●	●	-	●	●	136,50
118A	ARTICO man-made leather crystal grey not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59	●	●	●	●	●	●	●	-	●	●	273,00
151A	ARTICO man-made leather sports seat black only in conjunction with Code PEX and U59	○	○	○	○	○	○	○	-	○	○	0,00
161A	black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10	-	-	-	-	-	●	●	-	●	●	136,50
165A	almond beige / black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10	-	-	-	-	-	●	●	-	●	●	136,50
175A	Kunstleder - beige / schwarz certain countries only not in conjunction with code U10 only in conjunction with code P59	-	-	-	-	-	●	-	-	-	●	136,50
378A	ARTICO man-made leather / Maringá fabric crystal grey with white seams certain countries only	○	○	○	○	○	○	○	-	○	○	0,00

Valid from 08.10.2018 CY (809+059)

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	1	1	1	1	1	1	1	1	1	1	1	1	LLP
	not in conjunction with code P34 only in conjunction with code P59, U59													
381A	<b>ARTICO man-made leather / Maringá fabric black with white seams</b> certain countries only not in conjunction with code P34 only in conjunction with code P59, U59	0	0	0	0	0	0	0	0	-	0	0		0.00
411	<b>6-speed manual transmission</b> not in conjunction with code 239 not valid	S	-	-	-	S	S	0	-	-	-	-		0.00
429	<b>7G-DCT - dual clutch automatic transmission</b>  AMG SPEEDSHIFT DCT 7-speed sports transmission not in conjunction with code U64 Standard Certain countries only	S	S	S	S	-	-	-	S	S	S	S	0.00	1848.00
621A	<b>ARTICO man-made leather / Macapá fabric black</b> certain countries only only in conjunction with code P27, U59	0	0	0	0	0	0	0	0	-	0	0		0.00
625A	<b>ARTICO man-made leather / Macapá fabric sahara beige / black</b> certain countries only only in conjunction with code P27, U59	0	0	0	0	0	0	0	0	-	0	0		0.00
631A	<b>ARTICO man-made leather / Macapá fabric yellow ochre / black</b> certain countries only only in conjunction with code P27, U59	0	0	0	0	0	0	0	0	-	0	0		0.00
641A	<b>ARTICO man-made leather / DINAMICA microfibre AMG black</b> only in conjunction with Code PEZ and U59	-	-	-	-	-	-	-	-	0	-	-		0.00
651A	<b>ARTICO man-made leather / DINAMICA microfibre black</b> not in conjunction with code P34 only in conjunction with code 950 and U59 Standard	0	0	0	0	0	0	0	0	0	0	0		0.00
801A	<b>Leather black</b> only in conjunction with code P34 and U59 (in conjunction with Code 555 not with Code U59)	0	0	0	0	0	0	0	0	0	0	0		0.00
804A	<b>Leather nut brown</b> nly in conjunction with code P34 and U59 (in conjunction with Code 555 not with Code U59) not in conjunction with code 739	0	0	0	0	0	0	0	0	0	0	0		0.00
811A	<b>perforated leather black RED CUT</b> only in conjunction with code P39 and only with 873 and (U22 or 555); not with Code P34	0	0	0	0	0	0	0	0	0	0	0		0.00
831A	<b>Leather upholstery black</b> only in conjunction with code P73	0	0	0	0	0	0	0	0	-	0	0		0.00
855A	<b>Two-tone leather sahara beige / black</b> only in conjunction with code P34 and U59 (in conjunction with Code 555 not with Code U59)	0	0	0	0	0	0	0	0	0	0	0		0.00
22P	<b>Lane Tracking package</b> certain countries only only in conjunction with code 234, 476	●	●	●	●	●	●	●	●	●	●	●		819.00
30P	<b>Stowage Space package</b> only in conjunction with code 286, 932 and (939 or 682) (RHD); not in conjunction with code 555 only in conjunction with code 286, 939 and (932 or 682) (LHD); not in conjunction with code 555; certain countries only only in conjunction with code 555 but not in conjunction with code 286/932/939; certain countries only	●	●	●	●	●	●	●	●	●	0	●		157.50
430	<b>Off-road functions and presentation in MEDIA DISPLAY</b>	-	S	-	S	-	-	-	S	-	-	S		0.00
950	<b>AMG Line</b> certain countries only not in conjunction with code P27/P59/P73/951 or U37 only in conjunction with code (651A/801A/804A/811A/855A), (459/482/486 or 485), (633/635/655/RV1/RVJ/or 04R) and (498/U26/U66 or P34) only in conjunction with code 280 or 277 and (725 or 720+P55), 772, B59, (H79/H73/H92/739 or (P34 and (H06/H14/H19) or U63	●	●	●	●	●	●	●	●	●	-	●		2331.00
951	<b>Sports package USA</b> only in conjunction with code 460+P59+(635/655/RV1/RVJ)+772+(U12/P34); not in conjunction with 486/550/950/P27/U37 only in conjunction with code 494+P59+482+(635/655/RV1/RVJ)+772+(U12/P34); not in conjunction with 486/550/950/P27/U37	-	-	-	-	-	-	-	-	●	●	-	●	1615.95
B26	<b>AMG Aerodynamics package</b> only in conjunction with code P60 and U47 i.V.m. Code PEZ	-	-	-	-	-	-	-	-	●	-	-		1575.00
P17	<b>KEYLESS-GO Comfort-package</b> only in conjunction with Code 871, 889 and 890	●	●	●	●	●	●	●	●	●	●	●		966.00
P27	<b>Style</b> certain countries only not in conjunction with code 950/951/P59 only in conjunction with (105A/111A/118A/808/621A/625A/631A/ 801A/804A/811A/855A/831A), 280, 720 and (H54/H06/H14/H19/H73/H79 and P34/739 and P73/U63) and (R31/R48/01R/04R/08R/48R/65R/77R/82R/635/655/RV1 or RVJ)	●	●	●	●	●	●	●	●	●	-	●		441.00
P34	<b>Exclusive package</b>  not in conjunction with code P39 or PEZ not in conjunction with code PEX/P39/P73/U12 or U26 only in conjunction with code 873 and (889 or 893) and U09 and (H06/H14/H19/H73/H79/H91) and (U22/555) and (498/U26) and (801A/804A/855A) only in conjunction with code 280 and (H06/H14/H19/H73/H79/H54+P27 or (739/H81) and P59 or U63) and U22 and (801A/804A/855A) and (51U/55U but not with 830 or 58U) in conjunction with Code 950 in conjunction with Code P27 in conjunction with Code P59	-	0	0	-	0	-	0	-	0	-	0		1380.75
		★	★	★	★	★	★	★	★	★	★	★		2399,25
		★	★	★	★	★	★	★	★	★	★	★		
		●	●	●	●	●	●	●	●	-	●	●		1380.75
		●	●	●	●	●	●	●	●	-	●	●		1926.75
		0	0	0	0	0	0	0	0	-	0	0		1884.75
P39	<b>AMG Exclusive package</b> not in conjunction with code PEZ/P34 or (P73 (but not with AMG-Type)) only in conjunction with code 811A and (889/893) and (H19/H73/H79/H90/H92) and U09 and 498/U26) only in conjunction with code 811A, 889 or 893, (H19 and 460/494) or H73/H79 or H92, U09 and (498/U26) only in conjunction with code 950 and 811A and (889/893) and (H73/H79/H92/U63) and U09	0	0	0	0	0	0	0	0	0	0	0		1380.75
P47	<b>Parking Package with 360-degree camera</b> certain countries only	●	●	●	●	●	●	●	●	●	●	●		1312.50

20/8/2018 Optional extras for the GLA

Valid from 08.10.2018 CY (809+059)

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

		GLA										LLP	
Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	
	not in conjunction with code B28 only in conjunction with 235,501 and (P49 or (494,249 and 500))	GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	GLA 250 4MATIC Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 200 Sport Utility Vehicle RHD	GLA 220 4MATIC Sport Utility Vehicle	
P49	<b>Mirror package</b> certain countries only comprising: code 249, 500 i.V.m. Code P47	●	●	●	●	●	●	●	●	●	●	●	325,50 0,00
P54	<b>Anti-Theft Protection package</b> certain countries only comprising: code 551, 882, 817 (cert. countries only), 552 (cert.countries only)	○	○	○	○	○	○	○	○	○	○	○	0,00
P55	<b>Night package</b> certain countries only not in conjunction with code P60 only in conjunction with code 950, P27 or P59 and 720, (840 (certain countries only)), (01R/04R/48R/65R/655 or RVJ; not in conjunction with code U63 only in conjunction with code P59,720,840, and 01R/655 or RVJ in conjunction with Code 950 i.V.m. Code P59 i.V.m. Code PEX	●	●	●	●	●	●	●	●	-	●	●	787,50
P59	<b>Urban</b> not in conjunction with code 950, P27 only in conjunction with code 280, R31/R48/01R/04R/48R/77R/65R/82R/635/655/RVI or RVJ and (725 or 720+P55), 105A/111A/118A/161A/165A/168A/175A/381A,378A,801A,804A,811A/831A or 855A and 739/H73/H79/H81/ or (H06/H14/H19 and P34/P73) or U63	●	●	●	●	●	●	●	●	-	●	●	840,00 367,50 0,00
P60	<b>AMG Night package</b> only in conjunction with code 840 (cert. countries without 840) i.V.m. Code PEZ	-	-	-	-	-	-	-	-	○	-	-	703,50 0,00
P71	<b>AMG DYNAMIC PLUS package</b> consisting of code 281, 459 and 471 (certain countries only) in conjunction with 460/494 only in conjunction with 459, 471, 251 i.V.m. Code PEZ	-	-	-	-	-	-	-	-	●	-	-	2310,00
P73	<b>Exclusive Comfort package</b> certain countries only consisting of code 280, 873, (739/H06/H14/H19/H73/H54 and P27/(H79/H81) and P59/U63), U09, U22, 831A and (51U/58U) not in conjunction with code 950/U12/U26/P34 or P39 only in conjunction with code (889 or 893) i.V.m. Code P27 i.V.m. Code P59	●	●	●	●	●	●	●	●	-	●	●	2399,25
PAH	<b>AMG DINAMICA Cockpit package</b> only in conjunction with code 651A or 811A, L6G and H92 i.V.m. Code P71	●	●	●	●	●	●	●	●	-	●	●	1926,75 1884,75
PEX	<b>Night Edition</b> certain countries only not in conjunction with code (830/951/P34) only in conjunction with code P59 and 151A, H74 and (631/632) and 772 and (633/RVH/RVI/RVJ) and U09, U13 and U66 i.V.m. Code P55 ohne Code P55+633	-	-	-	-	-	-	-	-	●	-	-	892,50 367,50
PEZ	<b>AMG Night Edition</b> not in conjunction with (P34/P39) only in conjunction with code P60, B26 and (149U/191U/662U/696U/775U/787U) and 641A, H73, 555 and (E74/U03) and L6G, RVX and U26	●	●	●	●	●	●	●	●	-	●	●	3045,00 1968,75
U59	<b>Seat comfort package</b> not in conjunction with code 555 Standard i.V.m. Code U63/950 i.V.m. P27/P34/P39/P59/P73 i.V.m.Code P27/P34/P39/P59/P73	-	●	●	●	●	●	●	●	U	-	-	0,00 162,75
U62	<b>Light and sight package</b> certain countries only only in conjunction with Code 345, (543 (but not cert. countries)) and (U25 (but not cert. Countries))	S	S	S	S	S	S	S	S	S	S	S	0,00
U63	<b>Driving school package</b> certain countries only not in conjunction with code 840/P55/739/H06/H14/H19/H54/H73/H79 or H81 only in conjunction with code U59, U62, 931 only LHD in conjunction with Code U64	○	○	○	○	○	○	○	○	-	○	○	0,00
U90	<b>Low-Line package China</b> certain countries only	-	-	-	-	-	○	-	-	-	-	○	0,00
U92	<b>High-Line-package China</b> certain countries only	-	-	-	-	-	○	-	-	-	-	○	0,00
494	<b>USA specification</b>	-	-	-	-	-	○	○	○	○	-	-	0,00
498	<b>Japan specification</b>	-	-	-	-	○	-	○	○	-	-	○	0,00
709	<b>SKD vehicles for India</b>	○	-	○	-	-	-	-	-	-	○	-	0,00
712	<b>CKD delivery scope India</b> only 829L	-	-	-	-	-	○	○	-	-	-	-	0,00
713	<b>Omission of SKD parts Brazil</b>	-	-	-	-	○	○	○	-	-	-	-	0,00
714	<b>Omission of CKD parts Brazil</b>	-	-	-	-	○	○	○	-	-	-	-	0,00
719	<b>Indonesia SKD</b>	-	-	-	-	○	○	○	-	-	-	-	0,00
00B	<b>Owner's Manual and Service Booklet - Danish</b>	○	○	○	○	○	○	○	○	○	○	○	0,00
01B	<b>Owner's Manual and Service Booklet - Dutch</b>	○	○	○	○	○	○	○	○	○	○	○	0,00
01R	<b>45.7 cm (18-inch) 5-twin-spoke light-alloy wheels</b> in conjunction with code 645 not with R66 not in conjunction with code 950 in conjunction with Code P55	●	●	●	●	●	●	●	●	-	●	●	640,50
		○	○	○	○	○	○	○	○	-	○	○	0,00

Valid from 08.10.2018 CY (809+059)

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

Optional extras for the GLA		GLA																				LLP		
		156.908	GLA 200 d Sport Utility Vehicle	156.902	GLA 200 d 4MATIC Sport Utility Vehicle	156.903	GLA 220 d Sport Utility Vehicle	156.905	GLA 220 d 4MATIC Sport Utility Vehicle	156.942	GLA 180 Sport Utility Vehicle	156.943	GLA 200 Sport Utility Vehicle	156.944	GLA 250 Sport Utility Vehicle	156.946	GLA 250 4MATIC Sport Utility Vehicle	156.952	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	156.945	GLA 200 Sport Utility Vehicle RHD	156.947	GLA 220 4MATIC Sport Utility Vehicle	LLP
●	available at extra charge	●		●		●		●		●		●		●		●		●		●		●		168.00
S	standard equipment	-		-		-		-		-		-		-		-		-		-		-		0.00
U	annotations existing																							0.00
	C available at no extra charge																							0.00
	BM 156.945 nur Indien (RL) or Korea (LL)																							0.00
Code	Designation																							
	In conjunction with Code P59																							
01Z	Different topstitching certain countries only (830+700) and only i.c.w. (149U/896U)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.00
02B	Owner's Manual and Service Booklet - German																							0.00
03B	Owner's Manual and Service Booklet - Russian																							0.00
04B	Owner's Manual and Service Booklet - Finnish																							0.00
04R	45.7 cm (18-inch) multi-spoke light-alloy wheels certain countries only only in conjunction with code 645, R66 in conjunction with Code P55 or 950 in conjunction with Code P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	588.00
05B	Owner's Manual and Service Booklet - English																							0.00
06B	Owner's Manual and Service Booklet - Italian																							115.50
07B	Owner's Manual and Service Booklet - French																							0.00
07U	MB apps for Audio 20 without MBCONNECT certain countries only not in conjunction with code 11U, 362 only in conjunction with code 505/520 or 522	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	52.50
08B	Owner's Manual and Service Booklet - Spanish																							0.00
08R	43.2 cm (17-inch) multi-spoke light-alloy wheels certain countries only not in conjunction with code R66/P55/P59/950 only in conjunction with code R01 or 645	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0.00
09B	Owner's Manual and Service Booklet - Portuguese																							0.00
10B	Owner's Manual and Service Booklet - Swedish																							0.00
11B	Owner's Manual and Service Booklet - Arabic																							0.00
11U	Preinstallation for Remote Online in certain countries only with 531; in certain countries only with 505/520 or 522 not in conjunction with code 07U only in conjunction with code 362 Standard in cert. Countries i.V.m. Code 531/532	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	157.50
12B	Owner's Manual and Service Booklet - Engl. USA/CAN																							0.00
12U	Preinstallation for Concierge Service certain countries only	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.00
13B	Owner's Manual and Service Booklet - Norwegian																							0.00
14B	Owner's Manual and Service Booklet - Greek																							0.00
14U	Smartphone integration package not in conjunction with code 823L only in conjunction with code 16U and 17Ubut not in conjunction with code 823L i.V.m. Code 531/532	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	315.00
15B	Owner's Manual and Service Booklet - Turkish																							0.00
15U	Pre-installation for Mercedes-Benz Link only in conjunction Code 505/520 or 522	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0.00
16B	Owner's Manual and Service Booklet - Polish																							0.00
16U	Apple CarPlay only in conjunction with code 14U																							0.00
17B	Owner's Manual and Service Booklet - Czech																							0.00
17U	Android Auto only in conjunction with code 14U and (505/520/522/531/532)																							0.00
18B	Owner's Manual and Service Booklet - Engl. S. Am.																							0.00
18U	Baidu Carlife certain countries only and only in conjunction with code 14U and (520/522)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.00
19B	Owner's Manual and Service Booklet - French S. Am.																							0.00
1R0	winter (M+S) wheel and tyre assembly x 4 not in conjunction with code R66 only Germany	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	997.50
1R7	winter (M+S) wheel and tyre assembly x 4 not in conjunction with code R66 only Germany	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1480.50
20B	Owner's Manual and Service Booklet - Spanish S. Am.																							0.00
210	Literature in Swedish																							0.00
213	Sports Direct-Steer system certain countries only only in conjunction with code 486/459																							0.00
218	Reversing camera not in conjunction with code 501	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	351.75
21B	Owner's Manual and Service Booklet - Portug. S. Am.																							0.00
228	Auxiliary heater certain countries only certain countries only in conjunction with code B24 only LHD i.V.m. Code 362	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1312.50
22B	Owner's Manual and Service Booklet - Japanese																							1155.00
232	Garage door opener (frequency range 284-390 MHz) certain countries only only in conjunction with code U62, P49 (cert.countries only)	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	236.25
234	Blind Spot Assist certain countries only in conjunction with Code 22P	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	472.50
235	Active Parking Assist i.V.m. Code P47																							0.00
239	Active Distance Assist DISTRONIC certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	903.00

Valid from 08.10.2018 CY (809+059)

[illegible]

Valid from 08.10.2018 CY (809+059)

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

[illegible]

20/8/2018 Optional extras for the GLA

Valid from 08.10.2018 CY (809+059)

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

		GLA											
		156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
		GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	GLA 250 4MATIC Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 200 Sport Utility Vehicle RHD	GLA 220 4MATIC Sport Utility Vehicle	
		●	●	●	●	●	●	●	●	●	●	●	
		●	●	●	●	●	●	●	●	●	●	●	420.00
524	<b>Transport protection</b> certain countries only not in conjunction with code 820 only in conjunction with code 662U/000U oder Z98	●	●	●	●	●	●	●	●	●	●	●	168.00
531	<b>COMAND Online</b> only in conjunction with Code 351, 362, 367, 502, 513 and (11U and 12U (c.c.o)) i.V.m. Code 367	●	●	●	●	●	●	●	●	●	●	●	2740.50
532	<b>COMAND Japan</b> certain countries only only in conjunction with code 815 or 14U	-	-	-	●	-	-	●	●	-	-	-	3003.00
536	<b>Sirius satellite radio</b> certain countries only	-	-	-	-	-	-	●	●	●	●	●	1365.00
537	<b>Digital radio</b> (only certain countries) & not in conjunction with code Z97 only in conjunction with code 505/522/531	●	●	●	●	●	●	●	●	●	●	●	367.50
538	<b>ATTENTION ASSIST</b>	S	S	S	S	S	S	S	S	S	S	S	446.25
543	<b>Sun visor with illuminated vanity mirror</b> only in conjunction with code U62	○	○	○	○	○	○	○	○	○	○	○	0.00
550	<b>Trailer coupling with ESP® trailer stabilisation</b> certain countries only not in conjunction with code 459	U	U	U	U	U	U	U	U	-	U	U	0.00
551	<b>Anti-theft alarm system</b> only in conjunction with code P54 (certain countries only) in conjunction with Code P54	●	●	●	●	●	●	●	●	●	●	●	829.50
552	<b>Anti-theft alarm system</b> only in conjunction with code P54 and 513L	○	○	○	○	○	○	○	○	○	○	○	262.50
555	<b>AMG Performance seats</b> in conjunction with code 651A only in conjunction with U10 in conjunction with code 801A/804A/855A/811A or 641A only in conjunction with code 275, 241/242 and U10 invalid not in conjunction with code U22, U59 i.V.m. Code PEZ	U	U	U	U	U	U	U	U	U	U	U	0.00
55U	<b>Roof liner beige fabric</b> not in conjunction with code P73 only in conjunction with code P27 and (105A/625A) or P34 with 855A or P59 with 105A/165A/175A	○	○	○	○	○	○	○	○	-	○	○	1890.00
580	<b>Air conditioning system</b> certain countries only	S	S	S	S	S	S	S	S	S	S	S	0.00
581	<b>THERMOTRONIC automatic climate control</b> certain countries only only in conjunction with code P27/P34/P59/P73 or 950	●	●	●	●	●	●	●	●	●	●	●	0.00
58U	<b>Roof liner in crystal grey fabric</b> in conjunction with P34 only in conjunction with code 801A oder P73 not in conjunction with code P27 with code 105A/604A/625A or P59 not with code 105A/165A/175A or 950/P34 or P73	○	○	○	○	○	○	○	○	○	○	○	535.50
598	<b>Petrol particulate filter</b> only in conjunction with code 927	-	-	-	-	○	○	○	○	○	-	○	0.00
608	<b>Adaptive Highbeam Assist</b> only in conjunction with code 631 or 632	●	●	●	●	●	●	●	●	●	●	●	0.00
613	<b>Headlamps for RHD vehicles</b> certain countries only part of standard specification for LHD countries	○	○	○	○	○	○	○	○	-	○	○	105.00
620	<b>Halogen headlamps</b>	○	○	○	○	○	○	○	○	-	○	○	0.00
623	<b>Gulf States specification</b>	-	-	-	-	○	○	○	○	○	-	○	0.00
625	<b>Australia specification</b>	○	○	○	○	○	○	○	○	○	-	○	0.00
631	<b>LED High Performance headlamp (RHD)</b> only for certain countries Standard (cert. Countries only) i.V.m. Code PEX	-	●	●	●	●	●	●	●	U	-	○	0.00
632	<b>LED High Performance headlamp</b> only for certain countries Standard (cert. Countries only) i.V.m. Code PEX	-	●	●	●	●	●	●	●	U	-	○	918.75
633	<b>45.7 cm (18-inch) AMG 5-spoke light-alloy wheels</b> certain countries only in conjunction with code 645 not in conjunction with R66 not in conjunction with code P55 only in conjunction with Code 950 or PEX	○	○	○	○	○	○	○	○	-	○	○	0.00
634	<b>Omission of first-aid kit</b> certain countries only not in conjunction with code 820	○	○	○	○	○	○	○	○	○	○	○	0.00
635	<b>48.3 cm (19-inch) AMG 5-spoke light-alloy wheels</b> certain countries only in conjunction with code 645 not in conjunction with R66 in conjunction with code R01/R02 only in conjunction with code R66 not in conjunction with code P55 in conjunction with Code 950 in conjunction with Code P59	●	●	●	●	●	●	●	●	-	●	●	1365.00
636	<b>Omission of warning triangle</b> not in conjunction with code 820	○	○	○	○	○	○	○	○	○	○	○	472.50
645	<b>M+S winter tyres, set of 4</b> not in conjunction with code 460, 494, 498, 625, or 830	●	●	●	●	●	●	●	●	-	●	●	892.50
		●	●	●	●	●	●	●	●	-	●	●	115.50



Valid from 08.10.2018 CY (809+059)

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]



Valid from 08.10.2018 CY (809+059)

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

## 20/8/2018 Optional extras for the GLA

Valid from 08.10.2018 CY (809+059)

		GLA											
		156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
		GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	GLA 250 4MATIC Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 200 Sport Utility Vehicle RHD	GLA 220 4MATIC Sport Utility Vehicle	
	i.V.m. Code 242/950/P34/P73	●	●	●	●	●	●	●	●	●	●	●	152.25
	i.V.m. P59 ohne 105A/111A/118A	●	●	●	●	●	●	●	●	●	●	●	152.25
945	Emission control system China certain countries only	-	-	-	-	-	-	-	○	○	-	-	0.00
968	COC document EU6 without registration certificate part II certain countries only	○	○	○	○	○	○	○	○	○	○	○	0.00
969	COC document EU6 with registration certificate part II certain countries only	○	○	○	○	○	○	○	○	○	○	○	0.00
973	Designation as owner-driver rental vehicle	○	○	○	○	○	○	○	○	○	○	○	0.00
981	Omission of vehicle registration document	○	○	○	○	○	○	○	○	○	○	○	0.00
986	Identification no. (US-VIN) certain countries only	○	○	○	○	○	○	○	○	○	○	○	0.00
989	Identification label under windshield certain countries only; Standard certain countries only	○	○	○	○	○	○	○	○	○	○	○	0.00
997	Exhibition vehicle certain countries only	○	○	○	○	○	○	○	○	○	○	○	0.00
B02	Fanfare horn, electronic, for India	○	○	○	○	○	○	○	○	-	S	○	0.00
B03	ECO start/stop function	S	S	S	S	S	S	S	S	S	S	S	0.00
B08	Fanfare horn certain countries only	○	○	○	○	○	○	○	○	○	○	○	0.00
B12	Tyre-change toolkit (certain countries only) only in conjunction with code 690	●	●	●	●	●	●	●	●	●	●	●	31.50
B24	Remote control for auxiliary heater certain countries only only in conjunction with code 228	○	○	○	○	○	○	○	○	-	○	○	0.00
B28	AMG carbon-fibre exterior mirrors certain countries only not in conjunction with code 501 oder P47	●	●	●	●	●	○	○	○	○	●	●	210.00
B51	TIREFIT with tyre inflation compressor certain countries only in conjunction with code 645 only in conjunction with code 01R/65R/77R/R31/633/635/655 RVI or RVJ (cert. countries only) not in conjunction with code R66 (cert. Countries only) i.V.m. Code 362	○	○	○	○	○	○	○	○	○	○	○	0.00
B59	DYNAMIC SELECT AMG DYNAMIC SELECT	S	S	S	S	S	S	S	S	S	S	S	0.00
E64	ECALL RUSSLAND (GLONASS) certain countries only	●	●	●	●	●	●	●	●	●	●	●	472.50
E74	AMG sports stripes in matt graphite grey (decals) only in conjunction with PEZ	-	-	-	-	-	-	-	○	-	-	-	0.00
E76	Spare wheel certain countries only only in conjunction with code 669 only in conjunction with code 690	○	○	○	○	○	○	○	○	○	○	○	262.50
H06	matt black ash wood trim certain countries only not in conjunction with code U63 only in conjunction with code 950/P34/P27 or P73 only LHD i.V.m. Code P34/P73	●	●	●	●	●	●	●	●	●	●	●	273.00
H14	high-gloss brown burr walnut wood trim certain countries only not in conjunction with code U63 Only in conjunction with code P34, P27 or P73 only LHD i.V.m. Code P34/P73	○	○	○	○	○	○	○	○	○	○	○	0.00
H19	Satin-finish light brown poplar wood trim certain countries only not in conjunction with code U63 only in conjunction with code P34, P27 or P73 only LHD i.V.m. Code P34/P73	○	○	○	○	○	○	○	○	○	○	○	273.00
H54	Black matrix-look trim not in conjunction with code U63 only in conjunction with code P27	○	○	○	○	○	○	○	○	-	○	○	0.00
H73	AMG carbon-fibre trim not in conjunction with code U63 only in conjunction with code 950/P27/P34/P39/P59/P73 or PEZ (only AMG-Type) i.V.m. Code PEZ	●	●	●	●	●	●	●	●	●	●	●	945.00
H74	Carbon-fibre structure trim Only in conjunction with Code PEX	-	-	-	-	-	-	-	○	-	-	-	0.00
H79	light aluminium trim with longitudinal grain certain countries only in conjunction with code 950 not in conjunction with code U63 in conjunction with code P34 or P39 not in conjunction with code U63 (RHD) or Mercedes-AMG GLA 45 in conjunction with code P59 not in conjunction with code U63 and cert. Countries only i.V.m. Code P34/P39/P73/950	○	○	○	○	○	○	○	○	-	○	○	0.00
H81	Sail-pattern trim certain countries only not in conjunction with code U63 only in conjunction with code P59	○	○	○	○	○	○	○	○	-	○	○	0.00
H90	AMG Design trim in black / red	-	-	-	-	-	-	-	S	-	-	-	0.00

● available at extra charge    ○ available at no extra charge    ○ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Valid from 08.10.2018 CY (809+059)

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Option extras for the GLA		GLA											
		156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	
		GLA 200 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	GLA 250 4MATIC Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 200 Sport Utility Vehicle RHD	GLA 220 4MATIC Sport Utility Vehicle	
Code	Designation												LLP
	not in conjunction with code PEZ or P34												
H91	AMG Design trim in black / silver not in conjunction with code PEZ and certain countries only only in conjunction with code P34	-	-	-	-	-	-	-	-	○	-	-	0.00
H92	AMG trim in black DINAMICA microfibre certain countries only not in conjunction with code P34, PEZ only in conjunction with code 651A or 811A only in conjunction with code 950/951 or P39 only with 651A or 811A i.V.m. Code PAH	○	○	○	○	○	○	○	○	○	○	○	273.00
K08	Radio frequencies for South America certain countries only only in conjunction with code 505/520/522/531	○	○	○	○	○	○	○	○	○	○	○	0.00
K11	Adaptive brake lights certain countries only	○	○	○	○	○	○	○	○	○	○	○	0.00
L6G	AMG Performance steering wheel, microfibre DINAMICA black only in conjunction with code 651A or 641A or 811A i.V.m. Code P71 i.V.m. Code PAH/P74 i.V.m. Code PEZ	-	-	-	-	-	-	-	-	●	-	-	546.00
R00	43.2 cm (17-inch) steel wheels with 10-hole trim certain countries only not in conjunction with code P27, P55, P59, R66, 830, 950,951 only in conjunction with code R01 or 645	-	-	-	-	-	-	-	-	●	-	-	157.50
R01	Summer tyres in conjunction with code 633/R31/01R or 82R not with R66 (cert. countries only) in conjunction with code 633/R31/01R/82R only with R66 (cert. Countries only) only in conjunction with code (R00/R48/R67/08R/48R/65R/77R/635/655/RV1 or RVJ) (cert. countries only) only in conjunction with code 754/758/778/RVU/RVV/RVX/RVH or RVW	-	-	-	-	-	-	-	-	○	-	-	0.00
R02	All season tyres certain countries only only in conjunction with code 48R, 82R, R31, RV1, RVJ, 65R, 635, RUG or RUH	-	-	-	-	-	-	-	-	○	-	-	115.50
R05	Summer tyres, optimised rolling resistance certain countries only not in conjunction with code R66 only in conjunction with code R31/82R/01R or 633	-	-	-	-	-	-	-	-	○	-	-	0.00
R31	45.7 cm (18") 5-twin-spoke light-alloy wheels in conjunction with code R01 or 645 not in conjunction with code R66 not in conjunction with code P55,950,951 in conjunction with Code P59	○	○	○	○	○	○	○	○	○	○	○	609.00
R48	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels certain countries only in cert. countrie only in conjunction with P59; but not with R66 not in conjunction with code R66, P55, P59 or 950 in conjunction with Code P27	○	○	○	○	○	○	○	○	○	○	○	136.50
R66	Run-flat tyres in conjunction with code 04R only in conjunction with code 645 in conjunction with code 633/R31/01R/82R/635/655/48R/65R/77R/RV1 and RVJ only in conjunction with code R01 in conjunction with code R31/01R/82R635/655/48R/65R/RV1 or RVJ only in conjunction with code R02 not in conjunction with code B51(cert. Countries only)/754/758/778/R00/R05/R48/08R/1R0/1R7/2R4/4R6/5R1/RVU/RVV/RVX or RVW i.V.m. Code PEX+(RVH/RV1/RVJ)	○	○	○	○	○	○	○	○	○	○	○	52.50
R67	45.7 cm (18-inch) 5-spoke light-alloy wheels certain countries only (China)	○	○	○	○	○	○	○	○	○	○	○	0.00
R96	(20-inch) 5-spoke light-alloy wheels certain countries only	-	-	-	-	-	-	-	-	-	-	-	640.50
RVH	AMG - Vielspeichenräder 19" Rundum in conjunction with code 645 not in conjunction with R66 only in conjunction with PEX and P55	○	○	○	○	○	○	○	○	○	○	○	168.00
RVI	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels certain countries only in conjunction with code Code 645 not in conjunction with R66 in conjunction with code Code R01/R02 only in conjunction with R66 i.V.m. Code 950 i.V.m. Code 950+P55 i.V.m. Code P59	○	○	○	○	○	○	○	○	○	○	○	0.00
RVJ	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels certain countries only in conjunction with code Code 645 not in conjunction with R66 in conjunction with code Code R01/R02 only in conjunction with R66 i.V.m. Code 950 i.V.m. Code P59 i.V.m. Code PEX	○	○	○	○	○	○	○	○	○	○	○	1995.00
RVU	50.8 cm (20-inch) AMG multi-spoke alloy wheels not in conjunction with code R66 only in conjunction with code R01	○	○	○	○	○	○	○	○	○	○	○	1050.00
RVV	50.8 cm (20-inch) AMG multi-spoke alloy wheels not in conjunction with code R66 only in conjunction with code R01	○	○	○	○	○	○	○	○	○	○	○	682.50
RVX	AMG-VIELSPEICHENRAEDER 20" RUNDUM not in conjunction with code R66 only in conjunction with code PEZ and R01	○	○	○	○	○	○	○	○	○	○	○	1470.00
U01	Status display for rear seat belts in instrument cluster certain countries only	○	○	○	○	○	○	○	○	○	○	○	1575.00
U03	Omission of decals for special models	○	○	○	○	○	○	○	○	○	○	○	682.50
		○	○	○	○	○	○	○	○	○	○	○	1102.50
		○	○	○	○	○	○	○	○	○	○	○	0.00
		○	○	○	○	○	○	○	○	○	○	○	840.00
		○	○	○	○	○	○	○	○	○	○	○	

Valid from 08.10.2018 CY (809+059)

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Optional extras for the GLA					
Valid from 08.10.2018 CY (809+059)					
● available at extra charge    ○ available at no extra charge    U annotations existing S standard equipment    - not available - BM 156.945 nur Indien (RL) or Korea (LL)					
Code	Designation	GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle
	not in conjunction with code E74 not valid only in conjunction with code PEZ	*	*	*	*
U09	Upper section of dashboard in ARTICO man-made leather  only in conjunction with code P34, P39/P73 or PEX Standard I.V.m. Code P34/P39/P73 I.V.m. Code PEX	- ○ ○	- ○ ○	- ○ ○	S ○ ○
U10	Automatic deactivation of front passenger airbag  certain countries only not in conjunction with code 161A/165A/168A in conjunction with Code 108 (only ECE)	- ○	- ○	- ○	S ○
U12	Velour floor mats certain countries only not in conjunction with code 950/P34/P73	●	●	●	●
U13	"EDITION" badge on the wing not in conjunction with code 261 only in conjunction with code PEX	○	○	○	○
U17	Omission of designo seat belts in red only in conjunction with code 651A or 811A	-	-	-	○
U21	Sports exhaust system	-	-	-	●
U22	4-way lumbar support not in conjunction with code 555 only in conjunction with code U59 I.V.m. Code P34/P39/P73 I.V.m. Code PEZ	●	●	●	●
U25	Door sill panels with "Mercedes-Benz" lettering, illuminated AMG door sill panels with »AMG« lettering, illuminated only in conjunction with code U62	●	●	●	U *
U26	AMG floor mats certain countries only not in conjunction with code P34/P73 only in conjunction with code 950 (Cord floor mats with edging in black and black contrasting topstitching as well as AMG lettering)  only in conjunction with code PEZ only in conjunction with code PEZ (AMG floor mats with white "AMG" lettering and piping in white)	U * *	U * *	U * *	S * *
U35	Socket in load compartment only in conjunction with code 942	○	○	○	○
U37	Front fog lamps not in conjunction with code 950,951,772	●	●	●	-
U40	Partition net certain countries only not in conjunction with code 413	●	●	●	●
U43	LNT technology only in conjunction with code 927 and cert. Countries only	○	○	-	-
U47	AMG rear aerofoil certain countries only in conjunction with Code B26	-	-	-	●
U60	Active Bonnet certain countries only	S	S	S	S
U64	Full driving school package not in conjunction with code 429 only in conjunction with code U63 only LHD	●	-	●	-
U65	Additional exterior mirror right and left contains: code U63 only LHD	●	●	●	-
U66	Fußmatten Cord m.Einfassung in Schwarz u.weißer Kontrastziernaht sowie EDITION Schriftzug in weiß certain countries only not valid only in conjunction with code PEX	○	○	○	U *
U70	Red-painted brake callipers	-	-	-	●
Y05	designo seat belts in red  only in conjunction with code 651A or 811A	●	●	●	U *
Z83	Activation hill-start assist driving school only in conjunction with code U64	○	-	○	-
Z97	Electronic interface for remote control not in conjunction with code 537 only LHD models and certain countries only	●	●	●	●
Z98	Paint not feat.on standard sample card not in conjunction with code 830	○	○	○	○